

Notification to employees for learning and awareness

PSR05221

USEPA REG
0000454

| | | | | | | | | | | |
|----------------|---------|---|-----------|----|--------|---------|-----------------------|---|--|--|
| <u>1343349</u> | 2015-21 | Air hose in use without whip checks | 2/21/2015 | No | Closed | On Line | Brent Welsh | X | | |
| <u>1344508</u> | 2015-23 | Dropped wrench from heights through scaffolding | 2/23/2015 | No | Open | On Line | Trent Kies | X | | |
| <u>1364738</u> | 2015-30 | H2S alarm - checking seals on mid API | 3/18/2015 | No | Open | On Line | Nathaniel Biletnikoff | X | | |
| <u>1364767</u> | 2015-31 | H2S alarm at FAB area Tank Farm | 3/18/2015 | No | Closed | On Line | Burt Newbry | X | | |
| <u>1362343</u> | 2015-32 | Motor vehicle collision contractor parking lot | 3/18/2015 | No | Closed | On Line | Harry Nelson | X | | |
| <u>1368415</u> | 2015-34 | H2S Monitor alarm dumping samples to sink | 3/24/2015 | No | Open | On Line | Clancy Lien | X | | |
| <u>1366680</u> | 2015-35 | A bin slid off the side of the roll off truck. | 3/25/2015 | No | Open | On Line | Shawn Boyer | X | | |
| <u>1372265</u> | 2015-36 | H2S Monitor alarm - welding overhead | 3/26/2015 | No | Closed | On Line | Pamela Nolan | X | | |
| <u>1383757</u> | 2015-40 | Air compressor leak | 4/9/2015 | No | Closed | On Line | Becky Cullup | X | | |
| <u>1402237</u> | 2015-43 | Hydraulic fluid spray to face | 5/14/2015 | No | Closed | On Line | Clancy Lien | X | | |
| <u>1408940</u> | 2015-45 | Asbestos material discovered while removing wet insulation | 5/18/2015 | No | Open | On Line | Clancy Lien | X | | |
| <u>1404557</u> | 2015-47 | Loose friable asbestos at weld job site | 5/20/2015 | No | Closed | On Line | Lauri Fryxell | X | | |
| <u>1408870</u> | 2015-49 | Vehicle contact with overhead lines/conduit | 5/28/2015 | No | Open | On Line | Tom Wise | X | | |
| <u>1412616</u> | 2015-50 | Ladder cage installed causing people to duck to enter ladder cage | 6/1/2015 | No | Closed | On Line | Brent Welsh | X | | |
| | 2015-51 | Gas leak near tank 52 | 6/4/2015 | No | | On Line | Tanis Sims | x | | |
| <u>1416601</u> | 2015-53 | Plug dropped from height | 6/5/2015 | No | Closed | On Line | Trent Kies | X | | |
| <u>1418978</u> | 2015/55 | Beam clamp dislodged, dropped from height | 6/10/2015 | No | Closed | On Line | Kevin Williams | X | | |
| <u>1446655</u> | 2015-61 | DCU structure 4th/5th deck between 15-LX-2/5 missing handrail | 7/21/2015 | No | Open | On Line | Donald Danielson | X | | |
| <u>1447375</u> | 2015-62 | Cutting on a live steam line | 7/23/2015 | No | Open | On Line | Trent Kies | X | | |
| <u>1451232</u> | 2015-63 | red dye concentrate drip through gap in chem suit | 7/21/2015 | No | Open | On Line | Clancy Lien | X | | |
| | | | | | | | | | | |